



**NEW**

# VELOCITY ECONOMY HARNESS

## 1 Break-Away Lanyard Keepers

Lanyard keepers reduce the risk of dragging and snagging lanyards. The keeper is on the chest to make the lanyard end more accessible.

## 2 Identification

Now your employees can personalize their harnesses without jeopardizing the integrity of the webbing.

## 3 Finished Webbing Ends


Keeps the webbing ends from fraying or getting damaged as well as providing a clean and professional look.

## 4 Webbing Wear Indicator


Unique red webbing core provides a visual warning to the user that the webbing has been damaged and should be taken out of service.



[1]



[4]



Size	Chest	Legs	Velocity HUV		Velocity w/ 3 D-rings	
			Part#	Weight	Part#	Weight
S - L	Pass-Thru	Pass-Thru	01700	2.75	01702	3.00
XL - 2XL	Pass-Thru	Pass-Thru	01701	3.00		3.50
S - L	Pass-Thru	Tongue Buckle	01703	2.75	01705	3.00
XL - 2XL	Pass-Thru	Tongue Buckle	01704	3.00	01706	3.50

Your employees and customers will appreciate this higher quality economy harness for an incredible value. While other manufacturers look to cut costs by cheapening up their lower end products, Guardian Fall Protection proves that we will not sacrifice quality or the protection of your employees to save a few nickels and dimes.

The new Velocity Harness by Guardian Fall Protection brings the best economy harness to the market. Our engineers revamped the tired old basic harness into a higher quality product that your employees and customers will enjoy.

*Dual Lanyard Keepers:* Other manufacturers provide only one or none on their economy harness.

*Identification:* Now your employees can personalize their harnesses without jeopardizing the integrity of the webbing.

*Finished Webbing Ends:* Keeps the webbing ends from getting damaged as well as providing a clean and professional look.

*Webbing Wear Indicator:* The only economy harness on the market that provides a visual warning to the user and safety director that the webbing has been damaged and should be taken out of service.